

Manual

Hook weight up to 300
kg

wagPRO-H300

Table of contents

Specifications:.....	2
Set contents:.....	3
Safety:	3
Features:.....	3
Quick Help:	4

Specifications:

- **Warranty:** 1 year
- **Material:** Steel
- **Maximum nominal load:** 300 kg
- **Measurement accuracy:** +/- 50 g
- **Maximum permissible load:** 100% of nominal load
- **Scale Legalization:** No
- **Display:** 0.7 inch digital LCD
- **Display backlight:** blue
- **Additional functions:** screen pause, weight tare, unit swapping
- **Available weight units:** kg, lb
- **Power supply:** 3x AA batteries
- **Battery life:** up to 150 hours
- **Auto Power Off:** After 3 Minutes Of Inactivity
- **Working Temperature:** 10-40°C
- **Operating humidity:** up to 90% at 20 °C
- **Device dimensions:** 15 x 8 x 4.6 cm
- **Package dimensions:** 18.5 x 17.5 x 5 cm
- **Device weight:** 680 g
- **Weight with packaging:** 800 g

Set contents:

- Cash drawer with money compartments
- Two keys to the lock
- RJ12 plug cable
- Manual

Safety:

To keep your balance in good working order and to keep your measurement accurate, follow these recommendations:

- **DO NOT overload the balance** as this may damage the measuring system and void the warranty.
- **DO NOT place heavy objects for long periods of time**, as this may result in reduced accuracy and shortened lifespan of the measuring system.
- **ALWAYS check the condition of the scale** and handle before use.
- **IF THE BATTERY RUNS OUT, REMOVE THE OLD BATTERIES FROM THE OUTLET AND REPLACE THEM WITH NEW ONES.**
- **DO NOT use the scale** in rain/snow, storm, etc.
- **DO NOT repair the scale yourself** if it is damaged. In the event of a malfunction, please contact our customer service.

Features:

ON/OFF BUTTON

1. Press the "ON/OFF" button to start the balance when it is inactive. The scale will start the display and automatically zero
2. Press the "ON/OFF" button to turn off the scale

- When the scale is loaded and displays the value, press the "ON/OFF" button to save the scale as tare

TARE BUTTON

- Press the "TARE" button to lock the display. When "HOLD" is displayed, the screen will remain locked with the current value
- Press the "TARE" button to unlock the display. When the "HOLD" inscription disappears, the display will be unlocked and show real-time values

UNIT BUTTONS press the "UNIT" button to switch between the available weight units (kg, N, lb)

Quick Help:

Problem	Cause	Solution
No value on the display when the power button is active	Dead battery	Replace the battery
	Defective battery	
	Broken "TARE" button	Long press the power button
No response to pressing the "TARE" button	Broken "TARE" button	Clean and hold the "TARE" button for longer
Weight reading is unstable	The workpiece to be weighed is in motion	Stabilize the workpiece and weight to be weighed
	The scale is damp	Drain the scale
	Dust on the PCB	Vacuum the nooks and crannies of the scale

The value on the display is different than 0 without load	Weight not reset	Reset the balance with the "ON/OFF" button
	The scale has been stressed too long or too much	Hang the scale at rest for a long time
A big error in the weight reading	Weight not reset	Reset the balance with the "ON/OFF" button
	The weight is uncalibrated	Recalibrate the Balance
	Invalid unit	Change the unit with the "UNIT" button